

25X1A9a

ORIG:

UNIT:

EXT:

DATE:

MD/M/OSA

7509

23 MAY 67

CLASSIFIED MESSAGE

2000/09/11 : CIA-RDP71B00263R000200130003-1

S E C R E T

ROUTING	
1	D/M/OSA 9
2	D/M/OSA 10
3	D/O/OSA 11
4	IDEA/OSA 12
5	RB/OSA 13
6	14
7	15
8	16

DEFERRED	PRIORITY	INITIALS
ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

TO :

FROM:

CONF:

INFO:

TO 25X1A6c

S E C R E T

INFO

CITE

25X1A6c

INFO

25X1A6c

IDEALIST LOGS MAINT

RECENTLY ARTICLE 385 EXPERIENCED A FLAMEOUT DURING A

25X1A2g

ROUTINE TRAINING FLIGHT. [REDACTED] DIAGNOSED THE TROUBLE TO BE IN THE FUEL CONTROL. THE FUEL CONTROL WAS REMOVED AND REPLACED WITH THE FUEL CONTROL FROM ENG S/R 610397 AND THE BAD FUEL CONTROL WAS^{RE} INSTALLED ON ENG S/R 610397. THIS

25X1A2g

ENGINE IS BEING RETURNED TO [REDACTED] FOR SUBSEQUENT SCHEDULE

25X1A2g

TO [REDACTED] FOR "B" ENG CONV. REQUEST [REDACTED] SEND FUEL

25X1A2g

CONTROL S/R 39664 TO [REDACTED] FOR ANALYSIS TO DETERMINE

25X1A2g

DIFFICULTY AND ENG S/R 610397 BE PREPARED FOR SHIPMENT TO

25X1A2g

[REDACTED] FOR "B" ENG CONV. PLEASE ADVISE WHEN READY FOR SHIPMENT.

END OF MESSAGE

25X1A9a

COORDINATING OFFICERS

D/M/OSA

S E C R E T

RELEASING OFFICER

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.